

Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-2708
Inspection Date: 2026-07-23
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

A # 12233 - July 23, 2026, on site.

wellhead: SCVA ball valve handle was observed in the open position.

Kermit last reported gas production rate: 2026-05 "Active Status".

Signage is compliant to standards at road: no well location identifier/signage at well location.

Well Facility: Cata-Dyne regulator vent lines are present.

Storage: single wall tank (1x) in plastic containment, SDS labels present, and grounded.

Flowline: flowline is connected to wellhead, and well building, and pipeline.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100024916
Well ID: 12233
Well Name: CANLIN W LAPRISE C-A014-J/094-G-08
Location: NTS: C-A014-J/094-G-08

Authorized by BCER