

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2730
Inspection Date: 2026-07-29
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100022856
Well ID: 11497
Well Name: OVV SWAN D- 019-H/093-P-09
Location: NTS: D- 019-H/093-P-09

Permit: 100068773
Well ID: 25467
Well Name: OVV ECOG HZ SWAN D-A019-H/093-P-09
Location: NTS: D-A019-H/093-P-09

Permit: 100068774
Well ID: 25468
Well Name: OVV ECOG HZ SWAN D-B019-H/093-P-09
Location: NTS: D-B019-H/093-P-09

Permit: 100073584
Well ID: 27294
Well Name: OVV CRP HZ SWAN D-C019-H/093-P-09
Location: NTS: D-C019-H/093-P-09

Permit: 100073585
Well ID: 27295
Well Name: OVV CRP HZ SWAN D-D019-H/093-P-09
Location: NTS: D-D019-H/093-P-09

Permit: 100022856
Facility ID: 00019408
Facility Name: OVV SWANLAKE D-019-H/093-P-09 001
Facility Type: Well Facility
Location: NTS: D- 019-H/093-P-09

Permit: 100068773
Facility ID: 00024154
Facility Name: OVV HERITAGE D-019-H/093-P-09 004
Facility Type: Well Facility
Location: NTS: D- 019-H/093-P-09

Permit: 100068774
Facility ID: 00024155
Facility Name: OVV HERITAGE D-019-H/093-P-09 005
Facility Type: Well Facility
Location: NTS: D- 019-H/093-P-09

Permit: 100073584
Facility ID: 00025115
Facility Name: OVV HERITAGE D-019-H/093-P-09 006
Facility Type: Well Facility
Location: NTS: D- 019-H/093-P-09

Authorized by BCER