

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2735
Inspection Date: 2026-07-29
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100058922
Well ID: 22757
Well Name: OVV ECOG HZ SWAN A- 098-A/093-P-09
Location: NTS: A- 098-A/093-P-09

Permit: 100060440
Well ID: 22961
Well Name: OVV ECOG HZ SWAN A-A098-A/093-P-09
Location: NTS: A-A098-A/093-P-09

Permit: 100058922
Facility ID: 00022790
Facility Name: OVV HERITAGE A-098-A/093-P-09 001
Facility Type: Well Facility
Location: NTS: A- 098-A/093-P-09

Permit: 100060440
Facility ID: 00022882
Facility Name: OVV HERITAGE A-098-A/093-P-09 002
Facility Type: Well Facility
Location: NTS: A- 098-A/093-P-09

Authorized by BCER