

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2736
Inspection Date: 2026-07-29
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100070500
Well ID: 26102
Well Name: OVV HZ SWAN B- 092-B/093-P-09
Location: NTS: B- 092-B/093-P-09

Permit: 100070501
Well ID: 26103
Well Name: OVV HZ SWAN B-A092-B/093-P-09
Location: NTS: B-A092-B/093-P-09

Permit: 100070532
Well ID: 26105
Well Name: OVV HZ SWAN B-B092-B/093-P-09
Location: NTS: B-B092-B/093-P-09

Permit: 100070533
Well ID: 26106
Well Name: OVV HZ SWAN B-C092-B/093-P-09
Location: NTS: B-C092-B/093-P-09

Permit: 100070500
Facility ID: 00024498
Facility Name: OVV HERITAGE B-092-B/093-P-09 001
Facility Type: Well Facility
Location: NTS: B- 092-B/093-P-09

Permit: 100070501
Facility ID: 00024499
Facility Name: OVV HERITAGE B-092-B/093-P-09 002
Facility Type: Well Facility
Location: NTS: B- 092-B/093-P-09

Permit: 100070532
Facility ID: 00024500
Facility Name: OVV HERITAGE B-092-B/093-P-09 003
Facility Type: Well Facility
Location: NTS: B- 092-B/093-P-09

Permit: 100070533
Facility ID: 00024501
Facility Name: OVV HERITAGE B-092-B/093-P-09 004
Facility Type: Well Facility
Location: NTS: B- 092-B/093-P-09

Authorized by BCER