

## Inspection Report

Permit Holder: Ovintiv Canada ULC  
Inspection: 2026-2743  
Inspection Date: 2026-07-29  
Inspection Outcome: Inspected

**Inspection Comment:**

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100064308  
Well ID: 24024  
Well Name: OVV ECOG HZ SWAN B- 005-G/093-P-09  
Location: NTS: B- 005-G/093-P-09

Permit: 100064309  
Well ID: 24025  
Well Name: OVV ECOG HZ SWAN B-A005-G/093-P-09  
Location: NTS: B-A005-G/093-P-09

Permit: 100064310  
Well ID: 24026  
Well Name: OVV ECOG HZ SWAN B-B005-G/093-P-09  
Location: NTS: B-B005-G/093-P-09

Permit: 100064311  
Well ID: 24027  
Well Name: OVV ECOG HZ SWAN B-C005-G/093-P-09  
Location: NTS: B-C005-G/093-P-09

Permit: 100064308  
Facility ID: 00023453  
Facility Name: OVV HERITAGE B-005-G/093-P-09 001  
Facility Type: Well Facility  
Location: NTS: B- 005-G/093-P-09

Permit: 100064309  
Facility ID: 00023454  
Facility Name: OVV HERITAGE B-005-G/093-P-09 002  
Facility Type: Well Facility  
Location: NTS: B- 005-G/093-P-09

Permit: 100064310  
Facility ID: 00023455  
Facility Name: OVV HERITAGE B-005-G/093-P-09 003  
Facility Type: Well Facility  
Location: NTS: B- 005-G/093-P-09

Permit: 100064311  
Facility ID: 00023456  
Facility Name: OVV HERITAGE B-005-G/093-P-09 004  
Facility Type: Well Facility  
Location: NTS: B- 005-G/093-P-09

---

Authorized by BCER