

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2744
Inspection Date: 2026-07-29
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris but is completely grass covered. ESD(s) and scv(s) at wellhead are good. DW chem tank(s) is also good.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100058520
Well ID: 22669
Well Name: OVV ECOG SWAN C- 009-G/093-P-09
Location: NTS: C- 009-G/093-P-09

Permit: 100068761
Well ID: 25443
Well Name: OVV ECOG HZ SWAN C-A009-G/093-P-09
Location: NTS: C-A009-G/093-P-09

Permit: 100068762
Well ID: 25444
Well Name: OVV ECOG HZ SWAN C-B009-G/093-P-09
Location: NTS: C-B009-G/093-P-09

Permit: 100069232
Well ID: 25641
Well Name: OVV ECOG HZ SWAN C-C009-G/093-P-09
Location: NTS: C-C009-G/093-P-09

Permit: 100069237
Well ID: 25642
Well Name: OVV ECOG HZ SWAN C-D009-G/093-P-09
Location: NTS: C-D009-G/093-P-09

Permit: 100058520
Facility ID: 00022756
Facility Name: OVV HERITAGE C-009-G/093-P-09 001
Facility Type: Well Facility
Location: NTS: C- 009-G/093-P-09

Permit: 100068761
Facility ID: 00024146
Facility Name: OVV HERITAGE C-009-G/093-P-09 003
Facility Type: Well Facility
Location: NTS: C- 009-G/093-P-09

Permit: 100068762
Facility ID: 00024147
Facility Name: OVV HERITAGE C-009-G/093-P-09 004
Facility Type: Well Facility
Location: NTS: C- 009-G/093-P-09

Permit: 100069232
Facility ID: 00024259
Facility Name: OVV HERITAGE C-009-G/093-P-09 005
Facility Type: Well Facility
Location: NTS: C- 009-G/093-P-09

Permit: 100069237
Facility ID: 00024260
Facility Name: OVV HERITAGE C-009-G/093-P-09 006
Facility Type: Well Facility
Location: NTS: C- 009-G/093-P-09

Authorized by BCER