

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-2754
Inspection Date: 2026-07-28
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1305HRS.

Access road- Vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Location appears recently sprayed for weed control. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. Barricades in place. Signage at entrance. No positive isolation maintained. Valve handles not chained, locked and secure or removed. Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor.

Tank on site-No concerns at time of inspection.

Note- Deceased bird observed behind meter run (see attached).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100003637
Well ID: 02737
Well Name: CNRL ET AL W STODDART 11-19-086-20
Location: DLS: 11-19-086-20

Authorized by BCER



Inspection Number: 2026-2754
Inspection Date: 2026-07-28

Letter ID: L2603909
Letter Date: 2026-07-31