

Inspection Report

Permit Holder: Pavilion Energy Corp.

Inspection: 2026-2756

Inspection Date: 2026-07-28

Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1414HRS.

Access road- No concerns at the time of inspection.

Lease environment-No erosion sediment or water runoff concerns.

Lease Equipment: Pumpjack & Well appears active. ESD appears open. Chain link fence around pumpjack & well. Signage at entrance (warning decals fading).

Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor.

Pig Station- No concerns at time of inspection.

Tanks on site-No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100071202

Well ID: 26316

Well Name: PAVILION W STODDART 05-10-086-20

Location: DLS: 05-10-086-20

Permit: 100105963

Facility ID: 00026774

Facility Name: PAVILION STODDART 05-10-086-20 001

Facility Type: Satellite Battery

Location: DLS: 05-10-086-20

Permit: 100105963

Facility ID: 00026775

Facility Name: PAVILION STODDART 05-10-086-20 002

Facility Type: Well Facility

Location: DLS: 05-10-086-20



Inspection Number: 2026-2756
Inspection Date: 2026-07-28

Letter ID: L2603911
Letter Date: 2026-07-31

Authorized by BCER