

Inspection Report

Permit Holder: Pavilion Energy Corp.

Inspection: 2026-2758

Inspection Date: 2026-07-28

Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1535HRS.

Access road- No concerns at the time of inspection.

Lease environment- No erosion sediment or water runoff concerns.

Lease Equipment: Well appears active. Barricades in place. Signage in place.

Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor.

Tanks and secondary containment on site-No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100024548

Well ID: 12137

Well Name: PAVILION ET AL MONTNEY 06-31-086-19

Location: DLS: 06-31-086-19

Permit: 100024548

Facility ID: 00019498

Facility Name: PAVILION MONTNEY 06-31-086-19 001

Facility Type: Well Facility

Location: DLS: 06-31-086-19

Authorized by BCER