

## Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-2761

Inspection Date: 2026-07-30

Inspection Outcome: Inspected

### Inspection Comment:

Proximity to Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1440HRS.

Access road- No concerns at the time of inspection.

Lease environment- No erosion sediment or water runoff concerns.

Lease Equipment: Pumpjack & well suspended. No barricades in place (Limited risk due to isolated location). Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

Tanks and secondary containment on site-No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100037415

Well ID: 16215

Well Name: CNRL OSPREY D-A100-G/094-A-15

Location: NTS: D-A100-G/094-A-15

Permit: 100037415

Facility ID: 00020216

Facility Name: CNRL OSPREY D-100-G/094-A-15 001

Facility Type: Well Facility

Location: NTS: D- 100-G/094-A-15

---

Authorized by BCER