

Inspection Report

Permit Holder: Saba Oil & Gas Ltd.
Inspection: 2026-2766
Inspection Date: 2026-07-29
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

- active electric pumpjack. No SCVF
- location signage at the lease road is faded and missing symbols. Location signage on pumpjack is compliant and has both symbols.
- lease, access and location signage is compliant. Update the faded location sign at lease road.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001375
Well ID: 01070
Well Name: SABA O&G BOUNDARY 16-14-086-14
Location: DLS: 16-14-086-14

Authorized by BCER