

Inspection Report

Permit Holder: Whitecap Resources Inc.

Inspection: 2026-2767

Inspection Date: 2026-07-29

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-wellhead valves chained and locked. Flowline is disconnected from the wellhead.
Electric pumpjack in place disconnected from the polish rod. No SCVF. No polish rod in well.

-Lease, access and location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001154

Well ID: 00885

Well Name: WHITECAP ET AL BOUNDARY 06-24-086-14

Location: DLS: 06-24-086-14

Authorized by BCER