

Inspection Report

Permit Holder: Whitecap Resources Inc.

Inspection: 2026-2769

Inspection Date: 2026-07-30

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-electric pumpjack inactive at time of inspection. Wellhead valves are not chained and locked and flowline is not disconnected from the wellhead. Pumpjack in place connected to polish rod. No SCVF

-lease, access and location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100003851

Well ID: 02894

Well Name: WHITECAP ET AL BOUNDARY 03-01-086-14

Location: DLS: 03-01-086-14

Authorized by BCER