

Inspection Report

Permit Holder: Saba Oil & Gas Ltd.
Inspection: 2026-2774
Inspection Date: 2026-07-30
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

- active electric pumpjack. No SCVF
- there are two lined earthen pits with fencing on lease, what is the purpose of these pits?
- lease, access and location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100012814
Well ID: 07707
Well Name: SABA O&G BOUNDARY 02-02-086-14
Location: DLS: 02-02-086-14

Permit: 100012867
Facility ID: 00000895
Facility Name: SABA O&G BOUNDARYLAKE 02-02-086-14 001
Facility Type: Battery Site
Location: DLS: 02-02-086-14

Authorized by BCER