

Inspection Report

Permit Holder: Saba Oil & Gas Ltd.
Inspection: 2026-2776
Inspection Date: 2026-07-30
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

- active electric pumpjack. No SCVF
- There is vegetation growing around the wellhead 3'-4' high.
- lease, access and location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100030429
Well ID: 14102
Well Name: SABA O&G BOUNDARY 03-02-086-14
Location: DLS: 03-02-086-14

Permit: 100030985
Facility ID: 00007090
Facility Name: SABA O&G BOUNDARYLAKE 03-02-086-14 001
Facility Type: Battery Site
Location: DLS: 03-02-086-14

Authorized by BCER