

Inspection Report

Permit Holder: Saba Oil & Gas Ltd.
Inspection: 2026-2778
Inspection Date: 2026-07-30
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

- active electric pumpjack. No SCVF
- location signage at the lease road has a faded sour symbol and the flammable symbol is partially covered over. The location signage on the pumpjack is compliant.
- lease and access are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100041729
Well ID: 17559
Well Name: SABA O&G BOUNDARY 12-02-086-14
Location: DLS: 12-02-086-14

Permit: 100042581
Facility ID: 00007357
Facility Name: SABA O&G BOUNDARYLAKE 12-02-086-14 002
Facility Type: Battery Site
Location: DLS: 12-02-086-14

Authorized by BCER