

Inspection Report

Permit Holder: Saba Oil & Gas Ltd.
Inspection: 2026-2779
Inspection Date: 2026-07-30
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-electric pumpjack inactive at time of inspection. The database shows this well last produced in October 2025. No chain and lock on wellhead valves and no flowline disconnect from the wellhead. No SCVF. PJ remains connected to the polish rod.

-lease, access and location signage is compliant.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100030495
Well ID: 14114
Well Name: SABA O&G BOUNDARY 05-02-086-14
Location: DLS: 05-02-086-14

Permit: 100030984
Facility ID: 00007089
Facility Name: SABA O&G BOUNDARYLAKE 05-02-086-14 001
Facility Type: Battery Site
Location: DLS: 05-02-086-14

Authorized by BCER