

Inspection Report

Permit Holder: Saba Oil & Gas Ltd.
Inspection: 2026-2781
Inspection Date: 2026-07-30
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

- active electric pumpjack. No SCVF
- Lease is covered in foxtail barley and there is a 2-foot-deep rut down the middle of the access road which could be a hazard.
- location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100041728
Well ID: 17556
Well Name: SABA O&G BOUNDARY A06-03-086-14
Location: DLS: A06-03-086-14

Authorized by BCER