

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-2786

Inspection Date: 2026-08-04

Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1555HRS.

Access road- Limited vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Moderate vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place at entrance. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor. Building out of service.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100015829

Well ID: 08730

Well Name: CNRL BEAVERTAIL B- 068-A/094-A-15

Location: NTS: B- 068-A/094-A-15

Permit: 100015829

Facility ID: 00019146

Facility Name: CNRL BEAVERTAIL B-068-A/094-A-15 001

Facility Type: Well Facility

Location: NTS: B- 068-A/094-A-15

Authorized by BCER