

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-2787
Inspection Date: 2026-08-05
Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1125HRS.

Access road- Limited vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Moderate vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place, warning decals fading. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor. Building out of service.

Tanks on site- Out of service. No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100070034
Well ID: 25824
Well Name: TOURMALINE ET AL MARTIN C- 037-E/094-H-06
Location: NTS: C- 037-E/094-H-06

Permit: 100070034
Facility ID: 00024355
Facility Name: TOURMALINE MARTIN C-037-E/094-H-06 001
Facility Type: Well Facility
Location: NTS: C- 037-E/094-H-06



Inspection Number: 2026-2787
Inspection Date: 2026-08-05

Letter ID: L2603962
Letter Date: 2026-08-06

Authorized by BCER