

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-2789
Inspection Date: 2026-08-05
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1150HRS.

Access road- Vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Moderate vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. Barricades in place. Signage at entrance. Insulation from wellhead & flowline decaying and laying on ground and around lease (See attached). Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- Minor Flow detected from glove test. Glove partially filled in 2 min (see attached).

Building entry test- No alarms on personal monitor. Building out of service. Note: deceased bird on walkway beside building entrance (See attached).

Tanks on site-No concerns at time of inspection.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100006667
Well ID: 04684
Well Name: TOURMALINE ET AL MARTIN B- 023-H/094-H-05
Location: NTS: B- 023-H/094-H-05

Authorized by BCER



Inspection Number: 2026-2789
Inspection Date: 2026-08-05

Letter ID: L2603965
Letter Date: 2026-08-06