

Inspection Report

Permit Holder: Tourmaline Oil Corp.

Inspection: 2026-2790

Inspection Date: 2026-08-05

Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1232HRS.

Access road- No concerns at the time of inspection.

Lease environment- No erosion sediment or water runoff concerns.

Lease Equipment: D-74-G Wellhead Suspended. Barricades in place. Signage in place on wellhead. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

D-A74-G Wellhead Suspended. Barricades in place. Signage in place on wellhead. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

D-B74-G Wellhead Suspended. Barricades in place. Signage in place on wellhead. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100111404

Well ID: 40941

Well Name: TOURMALINE HZ Black D- 074-G/094-H-05

Location: NTS: D- 074-G/094-H-05

Permit: 100111404

Well ID: 40942

Well Name: TOURMALINE HZ Black D-A074-G/094-H-05

Location: NTS: D-A074-G/094-H-05

Permit: 100111404
Well ID: 40943
Well Name: TOURMALINE HZ Black D-B074-G/094-H-05
Location: NTS: D-B074-G/094-H-05

Authorized by BCER