

Inspection Report

Permit Holder: Cardinal Energy Ltd.
Inspection: 2026-2795
Inspection Date: 2026-08-07
Inspection Outcome: Inspected

Inspection Comment:

Site 04-03-082-14 was inspected at or about 0945hours, it was 14 & overcast.

The following was included in the inspection:

Access and signage: Signage clear and legible

Site: Wellsite clean and no vegetation concerns

Wellheads: Bull plugs, SCV, locks, leaks, - SCV no flow detected. Critical valves locked, spoke with operator regarding missing pollution pot lid

Chemical tanks: leaks, grounds, caps, - no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100024736
Well ID: 12202
Well Name: CARDINAL MICA 04-03-082-14
Location: DLS: 04-03-082-14

Permit: 100024736
Facility ID: 00019512
Facility Name: CARDINAL MICA 04-03-082-14 001
Facility Type: Well Facility
Location: DLS: 04-03-082-14

Permit Holder: Cardinal Energy Ltd.

Authorized by BCER