

## Inspection Report

Permit Holder: Cardinal Energy Ltd.

Inspection: 2026-2797

Inspection Date: 2026-08-07

Inspection Outcome: Inspected

### Inspection Comment:

Site 14-27-081-14 was inspected at or about 1030 hours, it was 14 & overcast.

The following was included in the inspection:

Access and signage: Signage clear and legible

Site: Wellsite clean and no vegetation concerns

Wellheads: Bull plugs, SCV, locks, leaks, - SCV no flow detected. Critical valves locked, no concerns

Meter/separator buildings: locks, leaks, caps, vents, - no concerns

Associated pipelines discontinued.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100006960

Well ID: 04903

Well Name: CARDINAL MICA 14-27-081-14

Location: DLS: 14-27-081-14

Permit: 100081448

Well ID: 30891

Well Name: CARDINAL HZ MICA B14-27-081-14

Location: DLS: B14-27-081-14

Permit: 100081448

Facility ID: 00026160

Facility Name: CARDINAL MICA 14-27-081-14 002

Facility Type: Well Facility

Location: DLS: 14-27-081-14

Permit Holder: Cardinal Energy Ltd.

---

Authorized by BCER