

Inspection Report

Permit Holder: Cardinal Energy Ltd.

Inspection: 2026-2798

Inspection Date: 2026-08-07

Inspection Outcome: Inspected

Inspection Comment:

Site 16-28-081-14 was inspected at or about 1045 hours, it was 14 & overcast.

The following was included in the inspection:

Access and signage: Signage clear and legible

Site: Wellsite clean and no vegetation concerns

Wellheads: Bull plugs, SCV, locks, leaks, - SCV no flow detected. Critical valves locked, no concerns

Riser & pig stations: chains, grounds, - no concerns

Product tank marked out of service

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100050394

Well ID: 20381

Well Name: CARDINAL MICA 16-28-081-14

Location: DLS: 16-28-081-14

Permit: 100055084

Well ID: 21456

Well Name: CARDINAL MICA A16-28-081-14

Location: DLS: A16-28-081-14

Permit Holder: Cardinal Energy Ltd.

Authorized by BCER