

Inspection Report

Permit Holder: ConocoPhillips Canada Resources Corp.

Inspection: 2026-2821

Inspection Date: 2026-08-07

Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1335HRS.

Access road- No concerns at the time of inspection.

Lease environment- No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. Barricades in place. Signage in place on wellhead (warning decals fading but visible). Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure (wing valve handles not chained). Surface casing vent flow test- No Flow detected from glove test.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100077367

Well ID: 28866

Well Name: COP HZ INGA 07-23-088-23

Location: DLS: 07-23-088-23

Permit: 100077367

Facility ID: 00025824

Facility Name: COP INGA 07-23-088-23 001

Facility Type: Well Facility

Location: DLS: 07-23-088-23

Authorized by BCER



Inspection Number: 2026-2821
Inspection Date: 2026-08-07

Letter ID: L2604011
Letter Date: 2026-08-10