

Inspection Report

Permit Holder: Enercapita Energy Ltd.

Inspection: 2026-2830

Inspection Date: 2026-08-06

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-the well looks to have been abandoned with all equipment remaining in place...ie: separator building, 400bbl tank (thief hatch open) with steel berm (tree has fallen across the berm and crushed it), chemical tank, flare stack (with underground FKO tank), and radio tower.

-piping is disconnected and tanks are labelled as "cleaned out in 2024".

-lease and location signage is compliant. Access is not maintained.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100018301

Well ID: 09673

Well Name: ENERCAPITA BOUNDARY 01-08-087-13

Location: DLS: 01-08-087-13

Authorized by BCER