

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-2835

Inspection Date: 2026-08-06

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-abandoned well. Only 2 pipeline risers (pig launch/receivers) remain onsite and a location sign.

-lease, access and location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100006059

Well ID: 04279

Well Name: CNRL ET AL BOUNDARY 10-05-087-13

Location: DLS: 10-05-087-13

Authorized by BCER