

## Inspection Report

Permit Holder: Enercapita Energy Ltd.

Inspection: 2026-2844

Inspection Date: 2026-08-06

Inspection Outcome: Inspected

### Inspection Comment:

#### COMMENTS:

-on August 6, 2026, I tried to access the well at 13-16-87-13 to do an inspection of the site. I got to approximately one kilometer from the lease but could not get to the lease as there are so many trees fallen across the access road. Please send me an email when this access has been cleared so that I can follow up with an inspection of this site.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100036339

Facility ID: 00020126

Facility Name: ENERCAPITA BOUNDARYLAKE 13-16-087-13 001

Facility Type: Well Facility

Location: DLS: 13-16-087-13

---

Authorized by BCER