

Inspection Report

Permit Holder: ConocoPhillips Canada Resources Corp.

Inspection: 2026-2875

Inspection Date: 2026-08-11

Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1005HRS.

Access road- No concerns at the time of inspection.

Lease environment- No erosion sediment or water runoff concerns.

Lease Equipment: A-7-A: Wellhead Suspended. Barricades in place. Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

A-a7-A: Wellhead Suspended. Barricades in place. Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

A-b7-A: Wellhead Suspended. Barricades in place. Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100037885

Well ID: 16264

Well Name: COP FIREWEED A- 007-A/094-A-13

Location: NTS: A- 007-A/094-A-13

Permit: 100050983

Well ID: 20633

Well Name: COP FIREWEED A-A007-A/094-A-13

Location: NTS: A-A007-A/094-A-13

Permit: 100052284
Well ID: 21007
Well Name: COP FIREWEED A-B007-A/094-A-13
Location: NTS: A-B007-A/094-A-13

Permit: 100050983
Facility ID: 00021845
Facility Name: COP FIREWEED A-007-A/094-A-13 003
Facility Type: Well Facility
Location: NTS: A- 007-A/094-A-13

Authorized by BCER