

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-2878

Inspection Date: 2026-08-11

Inspection Outcome: Inspected

Inspection Comment:

Proximity to Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1240HRS.

Access road- Vegetation growing on access road. Very muddy. No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place at entrance. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor. Building out of service.

Tanks and secondary containment on site- Out of service.

Note: various discarded equipment laying around lease (See attached).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100002668

Well ID: 02007

Well Name: CNRL ET AL CACHE D- 079-I/094-A-12

Location: NTS: D- 079-I/094-A-12

Permit: 100009661

Facility ID: 00000223

Facility Name: CNRL INGA D-079-I/094-A-12 001

Facility Type: Compressor Station

Location: NTS: D- 079-I/094-A-12

Permit: 100010710
Facility ID: 00000242
Facility Name: CNRL INGA D-079-I/094-A-12 002
Facility Type: Compressor Station
Location: NTS: D- 079-I/094-A-12

Authorized by BCER