

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-2880

Inspection Date: 2026-08-11

Inspection Outcome: Inspected

Inspection Comment:

Proximity to Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1310HRS.

Access road- Very muddy. No concerns at the time of inspection.

Lease environment- No vegetation on lease. Location appears to recently have had groundwork completed. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor. Building out of service.

Pig Station- Out of service.

Flare on site- Out of service.

Tanks and secondary containment on site-No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100000603

Well ID: 00470

Well Name: CNRL ET AL INGA B- 010-A/094-A-13

Location: NTS: B- 010-A/094-A-13

Authorized by BCER