

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-2914
Inspection Date: 2026-08-11
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

There are no 10-19 wells on this site only 11-19. Wells are on plunger lift systems. The meter run for the 11-19 well has a previous inspection date that is 2 years old.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100074086
Well ID: 27393
Well Name: CNRL HZ ALTARES 11-19-083-25
Location: DLS: 11-19-083-25

Permit: 100074087
Well ID: 27394
Well Name: CNRL HZ ALTARES A11-19-083-25
Location: DLS: A11-19-083-25

Permit: 100076344
Well ID: 28457
Well Name: CNRL HZ ALTARES B11-19-083-25
Location: DLS: B11-19-083-25

Permit: 100076345
Well ID: 28458
Well Name: CNRL HZ ALTARES C11-19-083-25
Location: DLS: C11-19-083-25

Permit: 100074086
Facility ID: 00025173
Facility Name: CNRL ALTARES 11-19-083-25 001
Facility Type: Well Facility
Location: DLS: 11-19-083-25

Permit: 100074087
Facility ID: 00025174
Facility Name: CNRL NORTHERNMONTNEY 11-19-083-25 002
Facility Type: Well Facility
Location: DLS: 11-19-083-25

Permit: 100076344
Facility ID: 00025666
Facility Name: CNRL NORTHERNMONTNEY 11-19-083-25 003
Facility Type: Well Facility
Location: DLS: 11-19-083-25

Permit: 100076345
Facility ID: 00025667
Facility Name: CNRL NORTHERNMONTNEY 11-19-083-25 004
Facility Type: Well Facility
Location: DLS: 11-19-083-25

Authorized by BCER