

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-2929
Inspection Date: 2026-08-14
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 0955HRS.

Access road- No concerns at the time of inspection.

Lease environment- No vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead appears active. Barricades in place. Signage in place at entrance. Surface casing vent flow test- No Flow detected from glove test. Building entry test- LEL alarms on personal monitor. Vented and retested- LEL detected on personal monitor.

Pig Station- No concerns at time of inspection.

Tanks on site-No concerns at time of inspection.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100031290
Well ID: 14400
Well Name: TOURMALINE ET AL BUICK D- 048-J/094-A-11
Location: NTS: D- 048-J/094-A-11

Authorized by BCER