

## Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-2935

Inspection Date: 2026-08-14

Inspection Outcome: Inspected

### Inspection Comment:

#### COMMENTS:

-Inactive pumpjack remains in place connected to the polish rod. Wellhead valves are chained and locked. Flowline is disconnected from the wellhead. Meter box and 100bbl tank remain in place.

-No SCVF, but handle is missing.

-lease, access and location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100043246

Well ID: 17877

Well Name: CNRL N BOUNDARY 06-07-087-14

Location: DLS: 06-07-087-14

Permit: 100043246

Facility ID: 00020700

Facility Name: CNRL BOUNDARYLAKENORTH 06-07-087-14 001

Facility Type: Well Facility

Location: DLS: 06-07-087-14

---

Authorized by BCER