

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-2936

Inspection Date: 2026-08-14

Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1405HRS.

Access road- No concerns at the time of inspection.

Lease environment- No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead appears active. Internal records indicate well last produced July 2026. Barricades in place. Signage in place at entrance. Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor.

Tanks on site-No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100021801

Well ID: 11176

Well Name: CNRL BIRCH B- 022-I/094-A-13

Location: NTS: B- 022-I/094-A-13

Authorized by BCER