

## Inspection Report

Permit Holder: Enercapita Energy Ltd.  
Inspection: 2026-2937  
Inspection Date: 2026-08-14  
Inspection Outcome: Inspected

### Inspection Comment:

#### COMMENTS:

- active pumpjack with anti-vibration shut down.
- No SCVF
- lease, access and location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100080341  
Well ID: 30369  
Well Name: ENERCAPITA HZ N BOUNDARY A14-29-087-14  
Location: DLS: A14-29-087-14

Permit: 100080341  
Facility ID: 00026087  
Facility Name: ENERCAPITA BOUNDARYLAKENORTH 14-29-087-14 001  
Facility Type: Well Facility  
Location: DLS: 14-29-087-14

---

Authorized by BCER