

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-2939

Inspection Date: 2026-08-14

Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1505HRS.

Access road- No concerns at the time of inspection.

Lease environment- No erosion sediment or water runoff concerns.

Lease Equipment: Pumpjack and Wellhead status unknown. Internal records indicate well last produced July 2026. ESD appears closed. Signage in place at entrance. Surface casing vent flow test- No Flow detected from glove test.

Tanks on site-No concerns at time of inspection.

Note: Pumpjack engine shack building removed and placed beside pumpjack (See attached).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100019117

Well ID: 09916

Well Name: CNRL HZ BIRCH C- 019-I/094-A-13

Location: NTS: C- 019-I/094-A-13

Authorized by BCER