

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-2941

Inspection Date: 2026-08-14

Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1513HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: D-19-I: Pumpjack and Wellhead Suspended. No Barricades in place (increased risk due to activity on location). Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Polish rod removed. Surface casing vent flow test- No Flow detected from glove test.

D-a19-I: Pumpjack and Well status unknown. Internal records indicate well last produced July 2026. No Barricades in place (increased risk due to activity on location). Signage in place. Surface casing vent flow test- No Flow detected from glove test.

Note: Strong odor downwind of wellhead, no alarm on personal monitor.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100006909

Well ID: 04866

Well Name: CNRL BIRCH D- 019-I/094-A-13

Location: NTS: D- 019-I/094-A-13

Permit: 100013922

Well ID: 08015

Well Name: CNRL HZ BIRCH D-A019-I/094-A-13

Location: NTS: D-A019-I/094-A-13

Permit: 100013922
Facility ID: 00019077
Facility Name: CNRL BIRCH D-019-I/094-A-13 002
Facility Type: Well Facility
Location: NTS: D- 019-I/094-A-13

Authorized by BCER