

Inspection Report

Permit Holder: Veresen Midstream General Partner Inc.

Inspection: 2026-2955

Inspection Date: 2026-08-14

Inspection Outcome: Inspected

Inspection Comment:

Met with Permit Holder representative and reviewed:

- * Master valve car seal list
- * Fixed Fire and Gas calibrations
- * Shutdown device calibrations
- * ESDV and ESD Button function tests
- * Panel checks for VRU and Recycle compressors
- * Flare and Incinerator flame fail device checks
- * Fugitive Emissions Survey
- * Reporting Meter calibrations
- * Monthly Tank Inspection template

Completed a joint site inspection:

- * ERP manual is current
- * Car seals installed on critical devices inspected
- * No faults or alarms on fixed fire and gas detector display screens

Good House keeping standards were noted on site and in building inspected.

Thank you for taking the time to review documentation and complete the site inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100052460

Facility ID: 00007466

Facility Name: VMGPI CUTBANK C-064-A/093-P-08 002

Facility Type: Gas Processing Plant

Location: NTS: C- 064-A/093-P-08

Permit: 100052461

Facility ID: 00007469

Facility Name: VMGPI CUTBANK C-064-A/093-P-08 003

Facility Type: Gas Sales Meter

Location: NTS: C- 064-A/093-P-08



Inspection Number: 2026-2955
Inspection Date: 2026-08-14

Letter ID: L2604194
Letter Date: 2026-08-18

Authorized by BCER