

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-2965
Inspection Date: 2026-08-18
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1224HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Well active, but currently not producing due to plant turnaround. ESD appears open. No barricades in place around wellhead (Limited risk due to isolated location). Signage in place at entrance. Insulated tape covering wellhead and flowline. Surface casing vent flow test- No Flow detected from glove test.

Tanks on site- Wet spot and staining below filter coming from corrosion inhibitor tank. Active dripping coming from filter from hydrate inhibitor tank (see attached). Officer spoke with field operator and was informed immediate action would be taken.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100074471
Well ID: 27444
Well Name: CNRL HZ BIRCH C- 011-J/094-A-13
Location: NTS: C- 011-J/094-A-13

Permit: 100074471
Facility ID: 00025204
Facility Name: CNRL BIRCH C-011-J/094-A-13 001
Facility Type: Well Facility
Location: NTS: C- 011-J/094-A-13



Inspection Number: 2026-2965
Inspection Date: 2026-08-18

Letter ID: L2604205
Letter Date: 2026-08-18

Authorized by BCER