

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2980
Inspection Date: 2026-08-19
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) and secondary containment meet current regulations.

Note: Packing on wellhead appears to be seeping.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100044382
Well ID: 16819
Well Name: OVV ECOG HZ NOEL C- 085-C/093-P-08
Location: NTS: C- 085-C/093-P-08

Permit: 100045951
Well ID: 19132
Well Name: OVV ECOG HZ NOEL C-A085-C/093-P-08
Location: NTS: C-A085-C/093-P-08

Permit: 100044382
Facility ID: 00020417
Facility Name: OVV DEEPBASIN C-085-C/093-P-08 001
Facility Type: Well Facility
Location: NTS: C- 085-C/093-P-08

Authorized by BCER