

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2981
Inspection Date: 2026-08-19
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100052452
Well ID: 20720
Well Name: OVV ECOG HZ CUTBANK D- 002-F/093-P-08
Location: NTS: D- 002-F/093-P-08

Permit: 100053195
Well ID: 20723
Well Name: OVV ECOG HZ CUTBANK D-A002-F/093-P-08
Location: NTS: D-A002-F/093-P-08

Permit: 100052452
Facility ID: 00021887
Facility Name: OVV DEEPBASIN D-002-F/093-P-08 001
Facility Type: Well Facility
Location: NTS: D- 002-F/093-P-08

Permit: 100053195
Facility ID: 00021889
Facility Name: OVV DEEPBASIN D-002-F/093-P-08 002
Facility Type: Well Facility
Location: NTS: D- 002-F/093-P-08

Authorized by BCER