

Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-2982
Inspection Date: 2026-08-20
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

WA# 16469 - Aug. 20, 2026: 12:36 hrs. on site.

Wellhead: SCVA ball valve handle was observed in the open position: no LEL gas was measured, and no flow was observed.

Kermit last reported gas production rate: 2026-06 "Active Status".

Signage is compliant to standards with comments: no wellhead location marker/sign is posted at wellhead; only visible placard is at well pad entrance.

Well Facility: Cata-Dyne regulator vent lines are present. Meter calibration date: 2026. Flare stack - out of service on site.

Storage: 1) single wall tank (1x) each on a metal containment, SDS present, and grounded and 2) Tanker - out of service on site.

Flowline: flowline is connected to wellhead, and well building, and pipeline - "Active Status".

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100038766
Well ID: 16469
Well Name: CANLIN LAPRISE A- 002-E/094-H-05
Location: NTS: A- 002-E/094-H-05

Permit: 100002636
Pipeline Project ID: 000001392
Segment IDs (Location): 7 (From NTS: A- 002-E/094-H-05 To NTS: D- 003-E/094-H-05)



Inspection Number: 2026-2982
Inspection Date: 2026-08-20

Letter ID: L2604227
Letter Date: 2026-08-21

Authorized by BCER