

Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-2987
Inspection Date: 2026-08-20
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

WA# 715 - Aug. 20, 2026: 12:26 hrs. on site.

Wellhead: SCVA: SCVF = no LEL gas was measured, and no flow was observed.

Kermit last reported gas production rate: 2025-04 "Suspended Status".

Signage is compliant to standards with comments: no wellhead location marker/sign is posted at wellhead; only visible placard is at well pad entrance. Signage visibility is obstructed by woody brush/vegetation.

Well Facility: Cata-Dyne regulator vent lines are present.
Operators/contractors are on site working on communication equipment.

Storage: double wall tanks (2x) each on a metal stand, SDS present, and grounded.

Flowline: flowline is connected to wellhead, well building, and pipeline - "Suspended Status".

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100000919
Well ID: 00715
Well Name: CANLIN LAPRISE A- 022-E/094-H-05
Location: NTS: A- 022-E/094-H-05

Permit: 100000919
Facility ID: 00018444
Facility Name: CANLIN LAPRISECREEK A-022-E/094-H-05 001
Facility Type: Well Facility
Location: NTS: A- 022-E/094-H-05



Inspection Number: 2026-2987
Inspection Date: 2026-08-20

Letter ID: L2604234
Letter Date: 2026-08-21

Authorized by BCER