

Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-3013
Inspection Date: 2026-08-20
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

WA# 7509 Aug. 20, 2026: 13:36 hrs. on site.

Wellhead: SCVA ball valve handle was observed in the open position: client is monitoring and reporting SCVA status/condition to standards.

Kermit last reported gas production rate: 2026-06 "Active Status".

Signage is compliant to standards with comments: no wellhead location marker/sign is posted at wellhead; only visible placard is at well pad entrance.

Storage: 1) single wall tank (1x) each on a metal containment, SDS present, and grounded. Flare stack is out of service.

Flowline: flowline is connected to wellhead, and well building, and pipeline - "Active Status".

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100012225
Well ID: 07509
Well Name: CANLIN LAPRISE D- 087-E/094-H-05
Location: NTS: D- 087-E/094-H-05

Permit: 100012225
Facility ID: 00019024
Facility Name: CANLIN LAPRISECREEK D-087-E/094-H-05 001
Facility Type: Well Facility
Location: NTS: D- 087-E/094-H-05

Permit: 100053030
Facility ID: 00007476
Facility Name: CANLIN LAPRISECREEK D-087-E/094-H-05 003
Facility Type: Compressor Station
Location: NTS: D- 087-E/094-H-05

Authorized by BCER