

Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-3014
Inspection Date: 2026-08-20
Inspection Outcome: Inspected

Inspection Comment:

WA# 16907 - Aug. 20, 2026: 13:10 hrs. on site.

Wellhead: SCVA ball valve handle was observed in the open position, no LEL gas was measured (Altair-5x), and no flow was observed.

Kermit last reported gas production rate: 2026-06 "Active Status".

Signage is compliant to standards: well location marker required at wellhead.

Well Facility: Cata-Dyne regulator vent lines are present: meter calibration record: 2026.

Storage: single wall tank (1x) in metal containment, SDS labels present, and grounded frame.

Flowline: flowline is connected to the wellhead, and well building, and to pipeline (Active Status).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100040375
Well ID: 16907
Well Name: CANLIN LAPRISE C- 069-E/094-H-05
Location: NTS: C- 069-E/094-H-05

Permit: 100040375
Facility ID: 00020451
Facility Name: CANLIN LAPRISECREEK C-069-E/094-H-05 001
Facility Type: Well Facility
Location: NTS: C- 069-E/094-H-05

Permit: 100041030
Pipeline Project ID: 000012827
Segment IDs (Location): 1 (From NTS: C- 069-E/094-H-05 To NTS: D- 069-E/094-H-05)



Inspection Number: 2026-3014
Inspection Date: 2026-08-20

Letter ID: L2604266
Letter Date: 2026-08-21

Authorized by BCER