

Inspection Report

Permit Holder: ConocoPhillips Canada Resources Corp.

Inspection: 2026-3045

Inspection Date: 2026-08-24

Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1519HRS.

Access road- No concerns at the time of inspection.

Lease environment- No vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure (wing valve handle not chained, locked & secure or removed). Surface casing vent flow test- No Flow detected from glove test.

Building not in service.

Note: Excavator and garbage contained on site.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100101612

Well ID: 32960

Well Name: COP HZ FIREWEED C- 010-H/094-A-13

Location: NTS: C- 010-H/094-A-13

Permit: 100103687

Facility ID: 00026533

Facility Name: COP FIREWEED C-010-H/094-A-13 001

Facility Type: Well Facility

Location: NTS: C- 010-H/094-A-13



Inspection Number: 2026-3045
Inspection Date: 2026-08-24

Letter ID: L2604314
Letter Date: 2026-08-24

Authorized by BCER