

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3067

Inspection Date: 2026-08-21

Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1216HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: A-42-G Well appears active. ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor. Needle valve missing plug, informed operator and was corrected within given timeframe. Operator provided Officer with photo documentation (see attached).

A-a42-G Well appears active. ESD unknown. Barricades in place. Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor.

A-b42-G Well appears active. ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor.

A-c42-G Well appears active. ESD unknown. Barricades in place. Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor.

A-d42-G Well appears active. ESD appears closed. Barricades in place. Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor.

Test Separator Building entry test- No alarms on personal monitor. No concerns at the time of inspection.

Tanks on site- No concerns at time of inspection.

Pig Station- No concerns at time of inspection.

Note: All meter calibration tags are out of date (see attached). Operator

states meters are currently being calibrated and will be completed September 2026.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100108220
Well ID: 39001
Well Name: CNRL HZ FIREWEED A- 042-G/094-A-13
Location: NTS: A- 042-G/094-A-13

Permit: 100108220
Well ID: 39002
Well Name: CNRL HZ FIREWEED A-A042-G/094-A-13
Location: NTS: A-A042-G/094-A-13

Permit: 100108220
Well ID: 39003
Well Name: CNRL HZ FIREWEED A-B042-G/094-A-13
Location: NTS: A-B042-G/094-A-13

Permit: 100108220
Well ID: 39004
Well Name: CNRL HZ FIREWEED A-C042-G/094-A-13
Location: NTS: A-C042-G/094-A-13

Permit: 100108220
Well ID: 39005
Well Name: CNRL HZ FIREWEED A-D042-G/094-A-13
Location: NTS: A-D042-G/094-A-13

Permit: 100109501
Facility ID: 00027097
Facility Name: CNRL FIREWEED A-042-G/094-A-13 001
Facility Type: Well Facility
Location: NTS: A- 042-G/094-A-13

Authorized by BCER