

Inspection Report

Permit Holder: Pacific Trail Pipelines Management Inc.

Inspection: 2026-3085

Inspection Date: 2026-08-21

Inspection Outcome: Inspected

Inspection Comment:

Inspection of maintenance activities along Hoult FSR right-of-way (ROW) on August 21, 2026.

- Stream 1 (S5): A culvert was installed at approximately km 6.0 of the Hoult FSR where a stream ford crossing previously existed. Riprap armouring is to occur at the culvert inlet and outlet. No flow was present in the stream at the time of inspection.
- Stream 2 (NCD): An existing 800 mm culvert was removed at approximately km 6.5 of the Hoult FSR. Accumulated debris was cleared and a new culvert was installed. Riprap armouring is to occur at the culvert inlet and outlet. No flow was present in the stream at the time of inspection.
- Stream 3 (S5): Works completed upstream of Hoult FSR at approximately km 9.0. Debris accumulation within the stream channel caused flows to overtop the channel and establish a new flow path parallel to the existing channel. The permit holder removed the debris and restored flow to the original channel. Riprap was placed along the channel bank to provide stability and reduce the potential for future overflow. The S5 stream was flowing clear at the time of inspection.
- The work area was observed to be orderly and well maintained, with disturbed areas limited to those necessary to complete the maintenance activities. The Hoult FSR was in good condition at the time of inspection, and no issues affecting vehicle access or road stability were observed.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100076400

Road Number: 02348

Segment IDs (Location): 001 (From NTS: B- 066-J/103-I-01 To NTS: D- 044-I/103-I-01)

Permit: 100121163

AACT Number: 00258429

Site Type: Workspace

Permit: 100121163

CIAS Number: 0010241

Location ID (Crossing Type): 1 (Culvert), 2 (Culvert), 3 (Debris Removal)

Permit: 100076400

Permit: 100121163

Authorized by BCER